

**Post-Hurricane Sandy Status Report for Region 2 Superfund Remedial Sites**  
**Located in Emergency Declaration Counties**

Full, Official Site Name: Standard Chlorine Chemical Company

Site Address or Location, including County: Kearny, Hudson County, NJ

Lat/Long for Site (if you can get this information):

Date of Inspection: 11/1/12

Name of Inspector: Enrique Castro

Affiliation of Inspector (EPA/Contractor/PRP/etc.): PRP (Tierra, Inc)

Best phone number to reach inspector:

Enrique Castro, 914-906-8035

Do conditions at the site pose an immediate threat to human health or the environment?

☐ Yes ☒ No

If Yes, please provide a brief description of the conditions and the necessary response actions:

Briefly describe any equipment damage, operational problems, etc.:

As of 11/1/12:

The flood water did not reach the floor elevation of the treatment plant building but it did reach some of the well control panels that were in low elevation areas. Once these panels are operational, the system will be restarted. The shipping containers where the recovered DNAPL is stored prior to disposal were dislodged by the surge. However, the drums within remained upright and there were no spills. The site caps do not appear to have been compromised but we will be conducting more thorough inspections in the coming days.